

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:						
Company	Dennis Ware Controller					
OGM	Steve Demczak Environmental Scientist III					

# **Inspection Report**

Permit Number:	C0070004 COMPLETE			
Inspection Type:				
Inspection Date:	Thursday, February 25, 2010			
Start Date/Time:	2/25/2010 2:00:00 PM			
End Date/Time:	2/25/2010 4:00:00 PM			
Last Inspection:	Thursday, January 28, 2010			

Inspector: Steve Demczak, Environmental Scientist III

Weather: Snow Covered 12 inches, Sunny

InspectionID Report Number: 2287

Accepted by: jhelfric

3/22/2010

Permitee: CASTLE GATE HOLDING CO
Operator: CASTLE GATE HOLDING CO

Site: CASTLE GATE MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

**Current Acreages** 

Total Permitted	7,619.00	
Total Disturbed	62.42	
Phase I	62.42	
Phase II	58.10	
Phase III		

**Mineral Ownership** 

✓ Federal
✓ State

✓ County
✓ Fee

Other

**Types of Operations** 

✓ Underground✓ Surface

✓ Loadout☐ Processing

Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violatios were issued.

The Permittee notified the Division that the required third quarter of 2009 surface water monitoring information for the Castle Gate Mine was in the DOGM EDI pipeline and was acceptable for uploading. All sites were monitored at the end of March and were reported as "no flow". The Permittee continues to meet the Special Condition included as Attachment "A" of the current State permit. There are no other "special" permit conditions.

The field conditions in Sowbelly and Hardscrabble Canyons remain virtually unchanged, as does the condition of the reclaimed area for Adit #1.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Monday, March 01, 2010

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070004 Inspection Type: COMPLETE

Inspection Date: Thursday, February 25, 2010

Page 2 of 3

## REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
   Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	$\checkmark$		<b>✓</b>	
2.	Signs and Markers	<b>✓</b>		<b>V</b>	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	<b>✓</b>		<b>~</b>	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring	<b>~</b>		✓	
4.e	Hydrologic Balance: Effluent Limitations		<b>✓</b>		
5.	Explosives		<b>V</b>		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	<b>✓</b>		<b>V</b>	
8.	Noncoal Waste	✓		<b>V</b>	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓		<b>V</b>	
11.	Contemporaneous Reclamation		<b>V</b>		
12.	Backfilling And Grading	<b>V</b>		<b>V</b>	
13.	Revegetation	<b>V</b>		<b>V</b>	
14.	Subsidence Control		<b>V</b>		
15.	Cessation of Operations		<b>V</b>		
16.a	a Roads: Construction, Maintenance, Surfacing		<b>V</b>		
16.b	Roads: Drainage Controls		<b>V</b>		
17.	Other Transportation Facilities		<b>V</b>		
18.	Support Facilities, Utility Installations	<b>V</b>		<b>V</b>	
19.	AVS Check	<b>V</b>			
20.	Air Quality Permit		<b>V</b>		
21.	Bonding and Insurance	<b>V</b>		✓	
22.	Other				П

Permit Number: C0070004 Inspection Type: COMPLETE

Inspection Date: Thursday, February 25, 2010

Page 3 of 3

# 1. Permits, Change, Transfer, Renewal, Sale

Castle Gate is in Phase II in reclamation. There are two sub-stations and a small area (Adit #1) that are in Phase I.

### 2. Signs and Markers

Identification signs are at the gates to the property.

### 3. Topsoil

All topsoil was used in reclamation.

### 4.a Hydrologic Balance: Diversions

Diversions were snow covered.

# 4.c Hydrologic Balance: Other Sediment Control Measures

The reclaim site is plocked for sediment control.

### 4.d Hydrologic Balance: Water Monitoring

The permittee has been submitted the third and fourth quater water data to the Division.

# 7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile at Goose Island was reclaimed.

#### 8. Noncoal Waste

The ground is snow covered.

### 10. Slides and Other Damage

No slides or damage was noticed during the inspection.

### 12. Backfilling And Grading

The sites are completely reclaimed. All backfilled material was used.

#### 13. Revegetation

All sites are revegetated.

### 18. Support Facilities, Utility Installations

There are no facilities at Castle Gate.

#### 21. Bonding and Insurance

The bonding amount is \$490,000. The insurance policy will expire on Dec. 13, 2010.